

1/7




FIG. 1A
(PRIOR ART)




FIG. 1B
(PRIOR ART)




FIG. 1C
(PRIOR ART)




FIG. 1D
(PRIOR ART)




FIG. 1E
(PRIOR ART)




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6A




FIG. 6B

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

LOCK1880

3/7




FIG. 7A




FIG. 7B




FIG. 7C





FIG. 7D

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

LOCK1880



4/7




FIG. 8




FIG. 9A

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

LOCK1880

5/7





FIG. 9B




FIG. 9C

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

LOCK1880

6/7




FIG. 9D

APPROVED	O.G. FIG.	
BY	CLASS	SUBCLASS
DRAFTSMAN		

LOCK1880

7/7





FIG. 10